



**COMISIÓN DE
INVESTIGACIÓN
DE ACCIDENTES
E INCIDENTES DE
AVIACIÓN CIVIL**

Report IN-015/2019

Incident involving a BOEING
B-737-524, registration LY-KLJ,
at the Getafe Air Base (Madrid)
on 5 April 2019



GOBIERNO
DE ESPAÑA

MINISTERIO
DE TRANSPORTES, MOVILIDAD
Y AGENDA URBANA

Edita: Centro de Publicaciones
Secretaría General Técnica
Ministerio de Transportes, Movilidad y Agenda Urbana ©

NIPO: 796-20-128-4

Diseño, maquetación e impresión: Centro de Publicaciones

COMISIÓN DE INVESTIGACIÓN DE ACCIDENTES E INCIDENTES DE AVIACIÓN CIVIL

Tel.: +34 91 597 89 63
Fax: +34 91 463 55 35

E-mail: ciaiac@mitma.es
<http://www.ciaiac.es>

C/ Fruela, 6
28011 Madrid (España)

Notice

This report is a technical document that reflects the point of view of the Civil Aviation Accident and Incident Investigation Commission (CIAIAC) regarding the circumstances of the accident object of the investigation, and its probable causes and consequences.

In accordance with the provisions in Article 5.4.1 of Annex 13 of the International Civil Aviation Convention; and with articles 5.5 of Regulation (UE) n° 996/2010, of the European Parliament and the Council, of 20 October 2010; Article 15 of Law 21/2003 on Air Safety and articles 1., 4. and 21.2 of Regulation 389/1998, this investigation is exclusively of a technical nature, and its objective is the prevention of future civil aviation accidents and incidents by issuing, if necessary, safety recommendations to prevent from their reoccurrence. The investigation is not pointed to establish blame or liability whatsoever, and it's not prejudging the possible decision taken by the judicial authorities. Therefore, and according to above norms and regulations, the investigation was carried out using procedures not necessarily subject to the guarantees and rights usually used for the evidences in a judicial process.

Consequently, any use of this report for purposes other than that of preventing future accidents may lead to erroneous conclusions or interpretations.

This report was originally issued in Spanish. This English translation is provided for information purposes only.

Contents

Abbreviations	4
Synopsis	6
1. FACTUAL INFORMATION	7
1.1. History of the flight.....	7
1.2. Injuries to persons.....	9
1.3. Damage to aircraft	9
1.4. Other damage.....	9
1.5. Personnel information	9
1.6. Aircraft information.....	10
1.7. Meteorological information	17
1.8. Aids to navigation.....	19
1.9. Communications	19
1.10. Aerodrome information.....	20
1.11. Flight recorders	22
1.12. Wreckage and impact information.....	27
1.13. Medical and pathological information.....	27
1.14. Fire.....	27
1.15. Survival aspects	27
1.16. Tests and research	27
1.17. Organizational and management information.....	27
1.18. Additional information	27
1.19. Useful of effective investigation techniques	28
2. ANALYSIS	29
3. CONCLUSIONS	31
3.1. Findings.....	31
3.2. Causes/Contributing factors	31
4. RECOMMENDATIONS.....	32
ANNEX 1. DESCRIPTION OF THE AUTOPILOT	33
A. (Auto Flight). General description and operation.	33
B. Mach / Airspeed indicators.....	34
C. Autopilot Flight and Director System.....	36
D. SPEED TRIM FAIL and MACH TRIM FAIL indications.....	41
ANNEX 2 COMPLETE FLIGHT PATH	43
ANNEX 3 FLIGHT PARAMETERS	44

Abbreviations

° ' "	Sexagesimal degrees, minutes and seconds
A/C	Aircraft
A/P	Autopilot
ADI	Altitude direction indicator
AESA	Spain's National Aviation Safety Agency
AFCS	Automatic flight control systems
AFDS	Autopilot flight director system
AMM	Aircraft Maintenance Manual
APP	Approach control service
ATPL(A)	Airline transport pilot license (airplane)
CAARL	Civil Aviation Authority of the Republic of Lithuania
CAO	Control Aéreo Operativo (coordinates civil-military traffic)
CPT	Captain
CVR	Cockpit voice recorder
CWS	Control wheel steering
DFCS	Digital flight control system
EADI	Electronic attitude direction indicator
EHSI	Electronic horizontal situation indicator
EYKA	Kaunas Airport, Lithuania
Ft	Feet
F/D	Flight director
F/O	First officer
FCC	Flight control computer
FCOM	Flight Crew Operating Manual
FDR	Flight data recorder
FMA	Flight mode annunciator
FMC	Flight management computer
G/S	Glide slope
GA	Go around
GS	Ground speed
h	Hours
HDG SEL	Heading select
HPa	Hectopascals
IFR	Instrument flight rules
ILS	Instrument landing system
IR(A)	Instrument rating (airplane)

Kg	Kilograms
Km	Kilometers
Kt	Knots
L	Left
Lb	Pounds
LEGT	Madrid Getafe Air Base
LEMD	Adolfo Suárez Madrid-Barajas Airport
LNAV	Lateral navigation
LOC	ILS localizer
m	Meters
MCP	Mode control panel
MEL	Minimum equipment list
METAR	Meteorological aerodrome report
N	North
PN	Part number
QNH	Altimeter sub-scale setting to obtain elevation when on the ground (Query Nautical Height)
R	Right
RA	Radio altimeter
RDMI	Radio distance magnetic indicator
Sn	Serial number
TAFOR	Terminal aerodrome forecast
TAS	True Airspeed
TCAS	Traffic collision avoidance system
TLB	Technical log book
TMA	Maintenance technician
TO	Takeoff
TO/GA	Takeoff /Go around
TWR	Tower
TWE GE	Getafe tower
UTC	Universal coordinated time
VFR	Visual flight rules
V _{MO}	Maximum operating speed
VNAV	Vertical navigation
VOR	Very high frequency omnidirectional range
W	West

Synopsis

Owner and operator:	UAB KLASEJET
Aircraft:	BOEING B-737-524, registration LY-
Date and time of incident:	KLJ 5 April 2019 at 14:54 h (local time ¹)
Site of incident:	Getafe Air Base (Madrid)
Persons on board:	65 (uninjured)
Flight rules:	IFR
Type of flight:	Commercial air transport. Landing.
Date of approval:	26 February 2020

Summary of event

On 5 April 2019, a BOEING B-737-524 aircraft, registration LY-KLJ, took off from the Adolfo Suárez Madrid-Barajas Airport (LEMD) en route to the Kaunas Airport (EYKA) in Lithuania.

It took off from runway 14L, with the captain's autopilot inoperative, and during the climb, the first officer's autopilot also became inoperative, so the crew decided to return to the departure airport without assistance from the automated systems.

After doing two go-arounds on runway 18L in adverse weather conditions, the crew declared an emergency and the aircraft was diverted by air traffic control to the Getafe Air Base (LEGT), in Madrid, where the aircraft landed on runway 23.

There were no injuries and the aircraft was not damaged.

The CIAIAC became aware of the event on 9 April and immediately contacted the operator to collect information. The next day, and in light of the data obtained, an investigation was opened and a lead investigator was appointed. One day later, the flight recorders were retrieved. The operator had sequestered them on the day of the incident but did not protect the information they contained, since the CVR recordings were unavailable.

The investigation has determined that the incident was caused by the problems the crew had operating the aircraft in instrument conditions following the loss of the aircraft's two automatic flight control systems.

¹ Unless otherwise specified, all times in this report are local. To obtain UTC, subtract two hours from local time.

1. FACTUAL INFORMATION

1.1. History of the flight

On 5 April 2019, the crew of a BOEING B-737-524 aircraft, registration LY-KLJ, was preparing for a planned flight from the Adolfo Suárez Madrid-Barajas Airport (LEMD) to the Kaunas Airport (EYKA) in Lithuania.

During the pre-flight inspection, they identified a fault in the captain's automatic flight system, so both pilots, with help from a company engineer, reviewed the Minimum Equipment List (MEL) and verified that it allowed dispatching the aircraft with this equipment inoperative.

They decided to proceed with the flight and after receiving the relevant clearance, took off from runway 14L at 14:15:26 h.

During the climb, several faults occurred with the first officer's automatic flight system, which eventually became inoperative at 14:17:32 h, so the crew decided to return to the departure airport while flying without assistance from the automatic flight systems.

Spain's air traffic control manager, ENAIRE, reported that shortly after takeoff, the crew declared an emergency but did not report the exact nature of their problem.

At 14:20 h, the operations supervisor informed the approach controller that he was transferring him an aircraft that had just taken off from Madrid-Barajas whose crew had declared an emergency and wanted to return to the airport.

Based on information provided by the controller, he cleared the runway 18R localizer by diverting two aircraft, AC/1 and AC/2, which were on approach to this runway. He also instructed them to adjust their speeds to maintain the required separation as much as possible, both to each other and to those that were already positioned at the localizer.

The traffic that declared an emergency did not lower its speed properly and crossed the two localizers at 250 kt behind a third aircraft, different from the two mentioned above, A/C 3.

The controller then corrected the approach vector he had initially provided so that the aircraft could intercept the localizer for runway 18L (180° heading).

The crew ended up going around at 14:23:10 h.

The controller asked if they had problems with the speed, since he did not know the nature of their emergency, but the crew again requested vectors to land.

Because of its position, the aircraft had to climb to maintain the minimum altitude, but the controller saw that it was not climbing.

He could not turn it toward Casas de Uceda because there were aircraft at the runway 18R localizer and it would have had to continue toward heading 360° to try to intercept it from behind.

Twice he informed the crew that they were below minimums and instructed them to climb, but they did not carry out this instruction, since the aircraft was at 4,400 ft and entering an area where the minimum was 6,700 ft.

It turned to 220° at 220 kt and positioned itself behind A/C 2, which was at the other localizer.

It managed to intercept the localizer 11 NM out, at an altitude of 4300 ft and a speed of 170 kt.

At 8 NM out, it had not acquired visual contact with the runway. Its speed was 150 kt.

It remained at the localizer, and the controller transferred the aircraft to a colleague who was on the final approach sequence (TWR 118.680) just before the aircraft reached a distance of 4 NM from the DME.



Figure 1. Photo of the aircraft at the air base

At a distance of 2.5 NM DME, it changed localizers and the controllers realized that it had gone around again. It was 14:33:58 h.

When the aircraft declared the emergency, the airport activated the local alert and the airport firefighters were standing by to respond to any situation during the landing on runway 18L.

After two failed landing attempts, the aircraft was diverted by air traffic control to the Getafe Air Base (LEGT) in Madrid, where it landed on runway 23 at 14:53 h.

There were no injuries and the aircraft was not damaged.

At Madrid-Barajas, the runway from which the aircraft had taken off was checked at 14:29 h. No foreign debris was found.

1.2. Injuries to persons

Injuries	Fatal	Serious	Minor/None
Crew			8
Passengers			57
Others			

1.3. Damage to aircraft

The aircraft landed undamaged.

1.4. Other damage

None.

1.5. Personnel information

The 56-year old pilot had an airline transport pilot license, ATPL(A), issued by the Civil Aviation Authority of Lithuania (Civilinės Aviacijos Administracija Lietuvos Respublika - CAALR) on 6 February 2006.

He had a B-737 300-900 type rating, an EMBRAER 170 type rating, an instrument rating, IR(A), and a type rating instructor, TRI(A), for the B-737 300-900. He had an English level of 4.

His license, ratings and medical certificate were all valid.

At the time of the incident, he had a total of 13,598 flight hours, of which 4,309 had been on the type, all of them as pilot in command.

The 34-year old first officer had an airline transport pilot license, ATPL(A), issued by the Civil Aviation Authority of Lithuania (CAALR) on 2 December 2016.

He had a B-737 300-900 type rating and an instrument rating, IR(A). He had an English level of 4.

His license, ratings and medical certificate were all valid.

At the time of the incident, he had a total of 2,260 flight hours, of which 2,000 had been on the type.

1.6. Aircraft information

1.6.1. General information

The Boeing B-737-524 is a transport airplane with a wingspan of 28.9 m, a length of 33.1 m and a total height of 11.13 m.

Its empty weight is 31,500 kg (69,445 lb) and its maximum takeoff weight is 70,080 kg (154,500 lb).

The incident aircraft, registration LY-KLJ, had serial number 28923 and a valid certificate of airworthiness, number 2022, issued by the Lithuanian Civil Aviation Authority on 26 June 2017. It was valid until 25 June 2019.

It was outfitted with two CFM-56-3C1 engines.

The aircraft's technical logbook listed the most recent maintenance tasks, done on the day of the incident, and the deferred items.

1.6.2. Normal procedures in the FCOM

The FCOM contains the following in its Normal Procedures.

Preflight Procedure – First Officer

The **first officer** normally does this procedure.

Mode control panelSet

COURSE(S)Set

FLIGHT DIRECTOR switch..... ON

Move the switch for the pilot flying to ON first.

Flight instrumentsCheck

Set the altimeter.

Airspeed cursor controlPush

Verify that the flight instrument indications are correct.

Verify that only these flags are shown:

- TCAS OFF
- expected RDMI flags

Verify that the flight mode annunciations are correct:

- autothrottle mode is blank
- actitud (pitch) mode is blank
- roll mode is blank
- AFDS status is FD

Preflight Procedure – Captain

The **captain** normally does this procedure.

Mode control panelSet

COURSE(S)Set

FLIGHT DIRECTOR switch..... ON

Move the switch for the pilot flying to ON first

Flight instrumentsCheck

Set the altimeter.

Airspeed cursor controlPush

Verify that the flight instrument indications are correct.

Verify that only these flags are shown:

- TCAS OFF
- expected RDMI flags

Verify that the flight mode annunciations are correct:

- autothrottle mode is blank
- actitud (pitch) mode is blank
- roll mode is blank
- AFDS status is FD

The same procedure also specifies that during the pre-flight procedure, both the captain and first officer have to place the F/D switches in ON, placing the F/D for the PF in the ON position first.

At this time, the crew also have to confirm that the airspeed cursor control is in the pushed position and verify that the flight instrument indications are correct, including the flags and flight mode annunciators.

Before taxiing, both pilots, the captain and first officer, check the recall function of the master caution light and verify that all the annunciator panel lights illuminate and then extinguish.

Before Taxi Procedure

RecallCheck C, F/O
Verify that all system annunciator panel lights illuminate and then extinguish.

A portion of the takeoff procedure contained in the B737 500 FCOM is provided below.

The FCOM, in the limitations section, states not to select the autopilot during takeoff when below 1000 ft AGL.

Take-off Procedure

Pilot Flying	Pilot Monitoring
Above 400 feet radio altitude, call for a roll mode as needed	Select and verify the roll mode
At thrust reduction height call "SET CLIMB THRUST"	
	Push the N1 switch
Verify that climb thrust is set	
After flap and slat retraction call "VNAV"	
	Push the VNAV switch
Engage the autopilot when above the minimum altitude for autopilot engagement	

1.6.3. Information on ITEM 34-01-04, Airspeed Cursor, in the Minimum Equipment List (MEL)

The Minimum Equipment List (MEL) has a section, Mach/Airspeed indications Airspeed cursor, the contents of which are described below:

34-01 Mach/Airspeed Indications

34-01-04 Airspeed Cursor

Interval	Installed	Required	Procedure
A	2	1	(O)

One may be inoperative provided:

- a. Alternate procedures are established and used.
- b. Repairs are made within three flight days.

PLACARD

Command Airspeed cursor is inoperative, placard near airspeed indicator -
COMMAND AIRSPEED CURSOR INOP

OPERATIONS (O)

When operating with an inoperative airspeed cursor, use external airspeed marker(s) (bugs) for speed reference.

Based on the above, only one of the two airspeed cursors installed on the airplane is required to be operative to dispatch the airplane, as long as it is repaired within three days and alternate procedures are established and used.

The operating procedure associated with it specifies that the speed bugs be used as a speed reference.

1.6.4. Flap extension speeds

Below is an extract from the B 737 500 FCOM containing the flap extension speeds.

Flap Extension Schedule (RSEP installed)			
Current Flap Position	At Speed (knots) a* / b* / c*	Select Flaps	Command Speed for Selected Flaps a* / b* / c*
Up	210 - 220 - 230	1	190 - 200 - 210
1	190 - 200 - 210	5	170 - 180 - 190
5	170 - 180 - 190	10	160 - 170 - 180
10	160 - 170 - 180	15	150 - 160 - 170
15	150 - 160 - 170	25	140 - 150 - 160
25	140 - 150 - 160	30 or 40	(VREF30 or VREF40) + wind additives

a* = At and below 117,000 lbs
b* = Above 117,000 lbs and up to 138,500 lbs
c* = Above 138,500 lbs

Flap Extension Schedule (RSEP installed)			
Current Flap Position	At Speed (knots) a* / b* / c*	Select Flaps	Command Speed for Selected Flaps a* / b* / c*
Up	210 - 220 - 230	1	190 - 200 - 210
1	190 - 200 - 210	5	170 - 180 - 190
5	170 - 180 - 190	10	160 - 170 - 180
10	160 - 170 - 180	15	150 - 160 - 170
15	150 - 160 - 170	25	140 - 150 - 160
25	140 - 150 - 160	30 or 40	(VREF30 or VREF40) + wind additives

a* = At and below 53,070 kgs
b* = Above 53,070 kgs and up to 62,823 kgs
c* = Above 62,823 kgs

Figure 7. Flap extension speeds

1.6.5. Aircraft maintenance

A review of the aircraft's technical logbook (TLB) since the day of the incident showed that the maintenance tasks on it were performed by six different maintenance technicians, identified in the TLB as follows. TMA 1 (TMA on board), TMA 2, TMA 3, TMA 4, TMA 5 and TMA 6

The maintenance done and the entries in the TLB are described below:

On 5 April 2019 at the Barajas Airport, before the incident flight, the daily check, done by TMA 1 is signed in TLB #02387. The same TLB shows a fault of the air speed cursor as a result of the failed test conducted by the pilots during the pre-flight inspection, which displayed a flag in the EADI. Because of this, the crew decided to defer the Air Speed Cursor Flag, as per MEL 34-1-04.

34-01 Mach/Airspeed Indications
34-01-04 Airspeed Cursor

Interval	Installed	Required	Procedure
A	2	1	(O)

One may be inoperative provided:

- a. Alternate procedures are established and used.
- b. Repairs are made within three flight days.

PLACARD

Command Airspeed cursor is inoperative, placard near airspeed indicator - COMMAND AIRSPEED CURSOR INOP

OPERATIONS (O)

When operating with an inoperative airspeed cursor, use external airspeed marker(s) (bugs) for speed reference.

Figure 8. MEL Section 34-01-04

After the incident, with the aircraft parked at the Getafe Air Base, the crew noted the following faults in technical log page (TLP) 02388:

- I. Auto pilot A and B Inop.
- II. Airspeed Cursor Flag (Left side)
- III. Time to time Speed trim and mach trim fail.

As a result of these entries, TMA 2 did the operational check of the autopilot as per AMM 22-11-33, with the result being Autopilot "A" = Fail and Autopilot "B" = OK.

- On 6 April 2019, TMA 2 deferred Autopilot "A" as per MEL Section 22-01A (TLP02394).
- On 9 April 2019, TMA 1 logged the replacement of the hydraulic pump module assembly in the TLB, as per AMM Section 29-15-95 (entry TLM02390).
- On 15 April 2019, the same TMA 2, replaced the "A" flight control computer (AFCC "A"), the "A" digital air data computer (DADC "A") and the accessory unit, which were annotated in the logbook as entry TLP02388.

He also logged a wiring inspection, finding and repairing an insulator in poor condition (entry TLP02395), and he expanded the HIL for the "A" autopilot.

There is no record of any entries involving the results of the checks after replacing the FCC or the DADC. According to the AMM, a test is required after these changes (AMM Section 22-11-33).

Had the test been done and yielded a satisfactory result, the deferred item could have been closed out; instead, the deferred item was extended. Neither the document for extending the deferred item nor the entry in the TLB for said extension could be found.

22-01 Autopilot Systems
22-01A One Autopilot System Required

Interval	Installed	Required	Procedure
C	2	1	

One required for CAT II operations.

Both required for AUTOLAND.

The altitude hold/level change functions of one autopilot is required for RVSM/ NAT HLA operations.

PLACARD

Mode Control Panel (MCP) – A/P ENAGAGE Panel – A(B) AUTOPILOT INOP

NOTE 1: Failures in one or both FCC's could affect these systems: Mach Trim (see MEL Item 22-05), Speed Trim (see MEL item 22-10), Flight Director (see MEL Item 34-12), and Altitude Alerting (see MEL item 34-25).

NOTE 2: One FCC must operate normally for the Speed Trim system to function.

NOTE 3: Failure in FCC A may affect the autothrottles (MEL item 22-04) on airplanes without an autothrottle computer.

Figure 9. MEL Section 22-01-A

That same day, TMA 1 logged in TLB 02392 the performance of JIC B71-00-03L (entry TLP02396).

The airplane flew from the Getafe Air Base to the Vilnius Airport (Lithuania). No entry was made regarding all of these previous faults.

- On 24 April 2019, due to the presence of "Autopilot A inop" in the HIL, #24, entry TLP 02398 was made in the job sheet (Job Sheet #02398) made by a TMA 3, as documented in the TLB. However, the job sheet was signed by TMA 5 and TMA 6 as the inspectors.

The entries make reference to the following actions:

- Troubleshooting performed that involved checking the entire cabling installation in the area of FCC "A". The built-in test equipment (BITE) was also used to run a test of the DFCS, specifically, the sensor values. The test showed that the hydraulic pressure switch for actuator "A" on the elevator was in the wrong position. As a result, both the actuator and the pressure switch were replaced. The hydraulic pressure switch on the autopilot for the elevator was also checked and the system was tested, with satisfactory results.
- Following these actions, deferred HIL entry #24 "Autopilot A inop", was closed out.
- On 24 April 2019, a test flight was conducted (entry TLP02400) by the same captain from the incident flight, who noted the following:
 - "DURING CLIMB APR. FL240 LOST OF EADI ON LH (BECOMES BLANK). AFTER 4 s POWER RESTORES AUTOMATICALLY ON EADI, EHSI. AUTOPILOT, FLIGHT DIR, AUTOTHROTTLE DISCONNECTS AUTOMATICALLY. YAW DAMPR STAYS IN OFF".
 - Subsequently, another operator, TMA 4, did troubleshooting as per AMM 34-22-00, which gave a "TEST FAIL SG", as a result of which the #1 symbol generator was replaced.
 - The troubleshooting was continued and relays C801, R3, R41 and R349 were replaced as per AMM 24-21-00. The AC generation system test was then performed again, giving a satisfactory result.

As per BOEING's recommendation, the inertial reference units (IRU) were replaced.

- On 20 April 2019, a test flight was carried out, with no faults being identified (entry TL).

1.7. Meteorological information

According to the meteorological information provided by Spain's National Weather Agency (AEMET), the general situation at low levels was dictated by a front that was crossing the peninsula, which caused showers and some storms as it passed and during the subsequent cold spell.

Remote sensing data and images showed an extensive area of clouds and precipitation affecting Madrid, with winds gusting up to 25 kt. At the time of the incident, there was heavy rain and abundant clouds, which reduced visibility considerably.

At the departure airport (Madrid Barajas), the forecast contained in the METAR and TAFOR reports was as follows:

**METAR COR LEMD 051130Z 16012KT 120V200 9999 BKN020 BKN040 08/05
Q0999 R88/CLRD// NOSIG=**

This corrected METAR was issued at 11:30 UTC. It indicated that the prevailing wind direction was from 160°, variable between 120° and 200° at 12 kt. Visibility was in excess of 10 km and there were broken clouds between 2,000 and 4,000 ft.

The temperature was 8° C, the dew point 5° C and the QNH was 999 hPa.

**METAR LEMD 051200Z 16014G24KT 110V190 9999 -RA BKN020 BKN040 09/06
Q0999 NOSIG=**

The 12:00 UTC METAR called for winds predominantly from 160°, variable between 110° and 190° at 4 kt, gusting to 14 kt. Visibility was in excess of 10 km. There was rain and broken clouds between 2000 and 4000 ft.

The temperature was 9° C, the dew point 6° C and the QNH was 999 hPa.

**METAR LEMD 051230Z 23017KT 6000 2500S SHRA SCT020TCU BKN025 07/04
Q0999 NOSIG=**

The 12:30 UTC METAR predicted winds predominantly from 230° at 17 kt. Visibility was 6 km. There were squalls and rain, as well as scattered clouds at 2,000 ft, and broken and towering cumulus clouds at 2,500 ft.

The temperature was 7° C, dew point 4° C, and QNH was 999 hPa.

**TAF LEMD 051100Z 0512/0618 22010KT 9999 BKN030 TX11/0515Z TN03/0606Z
PROB40 TEMPO 0512/0519 22015G25KT TEMPO 0512/0520 4000 RA SHRA
SCT030TCU PROB30 TEMPO 0512/0519 3000 TSRA SCT040CB PROB30 TEMPO
0606/0618 4000 RA SHRA BKN012 SCT040TCU PROB40 TEMPO 0611/0618
22020G32KT PROB30 TEMPO 0612/0618 3000 TSRA SCT030CB=**

The 11:00 UTC TAFOR predicted wind from 220° at 10 kt, visibility in excess of 10 km and broken clouds at 3,000 ft.

At the airport where it landed, the following METAR, SPECI and TAFOR reports were issued at around the time of the landing:

**METAR LEGT 051200Z 19012G22KT 7000 RA SCT012 BKN017 BKN035 08/06
Q0999=**

The 12:00 UTC METAR predicted wind predominantly from 190° at 12 kt, gusting to 22 kt. Visibility was in excess of 7 km, it was raining with scattered clouds at 1,200 ft and broken clouds between 1,700 and 3,500 ft.

The temperature was 8° C, dew point 6° C, and QNH was 999 hPa.

**SPECI LEGT 051208Z 22015G25KT 170V250 2500 +RA FEW007 BKN014 BKN017
06/03 Q0999=**

The 12:09 UTC SPECI predicted wind predominantly from 220, variable between 170° and 250°, at 12 kt, gusting to 25 kt. Visibility was 2,500 m. It was raining with few clouds at 700 ft and broken clouds between 1,400 and 1,700 ft.

The temperature was 6° C, dew point 3° C, and QNH was 999 hPa.

**TAF LEGT 051100Z 0512/0521 23010KT 9999 BKN030 PROB30 TEMPO
0512/0519 23015G25KT TEMPO 0512/0521 4000 RA SHRA SCT040TCU PROB30
TEMPO 0512/0519 3000 TSRA SCT040CB=**

The 11:00 UTC TAFOR, which was valid from 12:00 UTC until 21:00 UTC, forecasted wind from 230° at 10 kt. Visibility was in excess of 10 km, with broken clouds at 3,000 ft.

Wing gusts varying between 15 and 25 kt from 12:00 UTC until 19:00 UTC, rain and showers, clouds at 4,000 ft, as well as cumulus and cumulonimbus clouds at that same altitude.

1.8. Aids to navigation

Runway 18L at the Madrid-Barajas Airport has a category III ILS/DME that is available 24 hours a day. It is at coordinates 40° 31' 31.5" N - 003° 33' 29.6" W, and its DME is at an elevation of 585 m.

The Madrid-Getafe Airport has a VOR that broadcasts at a frequency of 112.050 MHz 24 hours a day. It is located at coordinates 40° 17' 23.4" N – 003° 43' 34.2" W, at an elevation of 624 m.

It also has an NDB that broadcasts 24 hours a day on 421.0 MHz. It is located at coordinates 40° 11' 59.2" N – 003° 50' 39.4" W.

For landings, it had a category I ILS for runway 23. It is also available 24 hours a day, and its localizer is located at coordinates 40°18' 12.7" N - 003° 42' 40.7" W and broadcasts on 338.8 MHz. It is at an elevation of 252 m.

1.9. Communications

A summary of the most relevant communications is provided below:

- At 14:39 h, the tower (TWR) at the Madrid-Barajas Airport contacted approach (APP) to report there was a traffic with an unknown problem that had some malfunctioning equipment and that had unsuccessfully attempted to land at Madrid-Barajas. The TWR also asked APP about the visibility.

In the minutes that followed, they exchanged weather information and reported they were going to send it to the Madrid-Getafe Airport.

- At 14:44 h, the TWR informed APP that the weather information had changed, and that visibility was 10,000 m, and asked if it would be able to land at the Madrid-Barajas Airport.
- At 14:45 h, there was a conversation between the TWR and CAO, in which the former reported that it was holding, that it had requested the METAR but that the landing airport was still unknown.
- At 14:46 h, APP spoke with the tower at the Getafe Airport (TWR GE) to report that the airplane was flying at 270 kt, which was very high, and in a holding pattern. TWR GE asked why it had not made an emergency landing at Madrid-Barajas, and APP replied that the crew could not see the airport. APP reported it had all traffic stopped, that they made the approach twice but did not want to land and that the crew's English was not good and they were unable to describe their emergency.
- At 14:47 h, the TWR GE communicated with another aircraft and reported that runway 23 was in use, with the wind from 260° at 13 kt.
- At 14:49 h, APP communicated with TWR GE to inform it that APP was going to send it to Getafe to land on runway 23. TWR GE gave the go-ahead, asked about the type of aircraft and then contacted the firefighters at the airport to inform them of the emergency and the type of aircraft involved.
- At 14:51 h, there were several conversations between the Scene Director and the firefighters at the Madrid Getafe Airport to prepare for the emergency.
- At 14:52 h, the TWR GE contacted the airplane to report the wind (250/14) and cleared it to land on runway 23, which the crew acknowledged.
- At 14:54 h, the airplane landed and the firefighters were cleared to cross the runway to take up a position close to the airplane.

1.10. Aerodrome information

1.10.1. Adolfo Suárez Madrid-Barajas Airport

According to information contained in ENAIRE's Aeronautical Information Publication (AIP), the Madrid-Barajas Airport is located 13 km northeast of the city and it is a 4E² airport, as per the ICAO categorization.

² The number 4 means the airport has a minimum reference field length of 1,800 m, and the letter E means that the aircraft operating must have a wingspan between 52 m and 65 m and outer main gear wheel span between 9 m and 14 m.

Its reference point is at an elevation of 609 m (1998 ft) and it has four pairwise parallel runways, designated 18R/36L, 18L/36R, 14R/32L and 14L/32R.

When the airport is operating in a north configuration, the 36 runways are used for takeoffs and the 32 runways for landings. When it is operating in a south configuration, the 14 runways are used for takeoffs and the 18 runways for landings.

The weather information office is open 24 hours.

1.10.2. Madrid Getafe Air Base

According to information contained in ENAIRE's AIP, the Madrid Getafe Air Base (LEGT) is a military airport that is located 15 km southwest of the city. Its reference point is at coordinates 40° 17' 39" N – 3° 43' 25" W, at an elevation of 619 m.

It has one runway in a 5/23 orientation that is 2,477 m long and 60 m wide. The aerodrome pattern is flown south of the runway.

It has a weather office that is open from 05:00 to 20:00 on Mondays, and from 05:00 to 19:00 on Fridays. The rest of the time, it is open as required by the needs of the unit. It issues METAR reports every hour and TAFOR reports every 9 hours.




Figure 10. Profile of the runway at the Madrid Getafe Air Base




Figure 11. Relative positions of the Madrid Barajas and Getafe Air Base airports

1.11. Flight recorders

The aircraft had a flight data recorder (FDR) and a cockpit voice recorder (CVR), which were retrieved on 11 April 2019 from their respective locations at the rear of the aircraft and downloaded at the CIAIAC laboratory.

1.11.1. Flight data recorder (FDR)

The FDR was an L3 FA 2100, with part number (PN) 2100-4043-00 and serial number (SN) 000001514.

Once the data were extracted and converted into engineering units at the CIAIAC laboratory, it was found that the engines were started at 13:58:17 h, and that the FDR started recording at 13:58:29 h, the time when the right engine was started.

The airplane began moving at 14:01:39 h, and at 14:14:54 h, it began its takeoff roll on runway 14L, going airborne at 14:15:26 h, with the intention of flying standard instrument departure RBO1U, which contains waypoints MD050 on heading 143°, MD051 on heading 117° and RBO on heading 9°.

The left-hand flight director (F/D B) was on during the entire flight, while the right-hand flight director (F/D A) was OFF during the entire flight.

The takeoff was performed with flaps 5 until 4700 ft³. At a GS of 204 kt (CAS of 202 kt), the flaps were retracted to 1°. They were fully retracted at 4200 ft, when its GS was 305 kt (CAS of 235 kt).

In the interval between flaps 1° and retracted, the aircraft began turns to the north and then to the northwest, with altitude changes between 4000 and 5000 ft.

At 14:15:31 h, the front gear was retracted, and the main gear was up at 14:15:33 h.

At 14:15:43 h, the lateral navigation system (LNAV) was engaged for 1 s, just as the airplane was climbing through a pressure altitude (PA) of 2852 ft.

At 14:15:58 h, while climbing through a PA of 3400 ft, N1 mode was set on the autothrottle (ATHR). The N1 compressor RPM reading went from 94% to 92%. This mode remained on until 14:17:32 h, at which time the FDR indicates that the ATHR was manually disengaged.




Figure 12. SID RBO1U from runway 14 L

At 14:16:02 h, while climbing through a PA of 3500 ft, the FDR recorded an attempt to engage the right-hand autopilot (AP B) in COMMAND (CMD) mode for 8 s. The FDR did not record any other attempts to engage the autopilot during this phase.

The GS remained around 170 kt and the pitch around 18° up to a PA of 4100 ft, at 14:16:14 h, at which point the pitch value decreased to between 8° and 10°. As the aircraft's nose lowered, the GS increased to 260 kt (CAS of 207 kt) at 14:16:50, with the aircraft at a PA of 4900 ft.

At 14:16:26 h, the FDR recorded MCP SPEED FCC engaged upon passing 4384 ft PA at a GS of 188 kt. At no time was AT MCP SPEED engaged. This means that the speed that the flight control computer had selected was set in the mode control panel, but not in the thrust lever.

³ Las altitudes están referidas a la altitud de presión.

At 14:16:50 h, the heading started to decrease, indicating turns to the north with changes in altitude between 4000 and 5000 ft (most of the time, the aircraft remained around 4500 ft).

Starting at 14:17:58 h, coinciding with the start of the turn to the north, the pitch angle was 3° up (ANU), with N1 ranging between 90% and 81%.

At 14:17:34 h, the GS peaked at 394 kt (CAS of 283 kt), the pitch angle recorded negative values as high as -11° (nose down – AND) and there were negative changes in altitude. At that point, the AT was disengaged and N1 was reduced to a value of 37%. The GS started to decrease from its maximum of 410 kt (at 14:17:42 h) to 312 kt (14:18:14 h).

During this time period, the FDR recorded a value for GS of between 260 and 410 kt, remaining at around 300 kt most of the time.

The aircraft stayed on a northerly course until 14:21:22 h, when it began to turn left to intercept the runway 18L localizer, but the turn was too wide, so the aircraft was unable to properly intercept the localizer from the left side (as seen from the cockpit), which is where the aircraft was coming from to later intercept it from the right side, at approximately 14:23:10 h, when its altitude was 5536 ft and its GS was 266 kt (CAS of 220 kt).

It then continued climbing until 14:23:36 h, reaching 5964 ft with a GS of 268 kt on a course of 176°. It had problems maintaining the correct altitude and position with respect to the ILS localizer and the glide slope.

It started to descend, maintaining the descent rate and the same deviations from the localizer and glide slope until 14:25:43 h, when it reached its minimum altitude of 3296 ft. This may be considered as the point when it initiated the first go-around.

According to ATS, it turned to heading 110° at a GS of 276 kt.

It continued climbing while turning left and at 14:27:36, it steadied on course north with a GS of 314 kt. It stayed on that course for 1:38 minutes while climbing, but not continuously.

At 14:29:14 h, it started turning left while changing its altitude noticeably.

At 14:30:10 h, when it was at 4989 ft at a GS of 272 kt on heading 279°, it started climbing again, reaching 5784 ft at 14:31:02 h on a heading of 206° and a GS of 170 kt, which is when the second approach to LEMD may be said to have started.

During the entire climb after the first landing attempt, the crew increased the angle of the flaps, first to 5° and then to 10°, which is the position they were in when the second descent was initiated.

At 14:33:03 h, the nose gear was down, and 2 s later the main gear was down.

At 14:36:51 h, it reached its minimum altitude of 2604 ft and aborted the landing a second time. Its heading was 203° and its GS was 176 kt. The crew was still having problems maintaining the ILS localizer and glide slope. During the descent, the flaps were lowered to 15° at first and then fully extended, equivalent to a deflection of 30°.



After going around, the airplane began to climb as it turned right. It then proceeded to the Getafe Air Base (LEGT) after being diverted by ATS. The flaps were extended at 14:23:42 h, during the first landing attempt at LEMD, and they were kept extended in various positions until 14:37:48 h, by which time it was already climbing while proceeding to LEGT after the second go-around.

At 14:41:42 h, it reached an altitude of 7864 ft, which was the highest of the entire flight, and it began the descent to runway 23 at LEGT on a course of 229° and a GS of 298 kt.

During the descent, there were minor variations in speed and heading until 14:44:31 h, when the airplane started to climb again while deviating to the right.

Between 14:44:31 h and 14:47:09 h, the aircraft circled south of the runway in the vicinity of the beacon designated GE, at an altitude between 6688 and 6440 ft. Its flaps were not deployed.

It kept turning left while descending to fly the right downwind leg for runway 23.

The crew lowered the flaps at 14:49:24 h, first 1°, then 5°, 15° and 30°, which was their position during the landing.

At 14:50:43 h, it was on the runway heading (229°) with a GS of 170 kt at an altitude of 3520 ft. It eventually landed at 14:52:28 with a GS of 160 kt (CAS of 145 kt).




Figure 14. Approach to runway 23 at Getafe

1.11.2. Cockpit voice recorder (CVR)

The CVR, made by Honeywell, with PN 980-6022-001 and SN 04870, was also removed from its housing on the same day as the FDR.

Four channels of audio were downloaded at the CIAIAC laboratory, but the incident flight was not recorded. It is not known why the audio associated with the incident was not recorded.

1.12. Wreckage and impact information

The landing at the Madrid-Getafe Air Base was normal. The aircraft was not damaged and none of the persons on board was injured.

1.13. Medical and pathological information

Not applicable.

1.14. Fire

There was no fire.

1.15. Survival aspects

While attempting to land at the Madrid-Barajas Airport, a local emergency and alert were declared and the firefighters were standing by on runway 18L to provide assistance.

At the Madrid-Getafe Airport, the firefighters were deployed to assist during the landing on runway 23, and they aided in disembarking the passengers by setting up a telescoping rising platform and a hydraulically-actuated boarding staircase, as well as a ground power unit.

1.16. Tests and research

It was not necessary to conduct any special tests or research.

1.17. Organizational and management information

Not applicable.

1.18. Additional information

The operator wrote a report on its investigation into the event that contains recommendations involving:

- Practicing manual flying, including in adverse weather scenarios, without help from the automatic systems.
- A review of the decision-making and crew cooperation processes.
- Additional CRM training for the crew and incompatibility between the two members that make up the same crew.
- Monitoring the defects involving the autopilot system.

1.19. Useful of effective investigation techniques

It was not necessary to use any special investigation techniques.

2. ANALYSIS

When analyzing this event, the first thing to note is the fact that having both autopilots become inoperative did not prevent proceeding with the flight in instrument conditions, since the instruments required to carry out a flight of these characteristics were available to the crew at all times; namely, they had the artificial horizon, altimeter, variometer, anemometer, compass, turn and bank indicator and the engine instruments (intake pressure and engine pressure ratio).

The crewmembers had instrument flight ratings and, based on the information gathered, had considerable experience, both in general and on the type.

In the case of the captain, he was a type rating instructor (TRI(A)), meaning he was not only very familiar with the airplane, its systems and its operation, but he had to be able to explain these concepts, that is, to convey them during training to other crewmembers in an operational setting, and to other pilots in general in a training setting.

If the first officer was the pilot flying (PF), it was because the captain noticed that the air speed cursor flag on his own side was inoperative, and since it is the captain who has to know all the aircraft systems well, he might have thought that the flight computer was affected. They therefore engaged the computer on the other side to do the flight.

An analysis of the data recorded on the FDR does not show any attempt to engage the autopilot on the captain's side (AP A). The flight director on that side (F/D A) was off from the start of the flight, although it should have been on, since the F/D is independent from the autopilot. The crew had set up the cockpit to have both the AP and F/D on the first officer's side be the master, meaning they were turned on first so that for both systems, the ones on the right side provided the guidance. The AP were inoperative, but if both F/D had been on, the indications provided would have been from the right side.

However, the data recorded in the FDR show that the F/D display on the left side was off, meaning the captain did not have guidance from the F/D on his side.

The data recorded in the FDR clearly indicate that they had considerable problems maintaining the basic flight parameters (altitude, speed, heading, etc.). This is most obvious when analyzing the turns.

The bad weather conditions complicated the operation.

There was turbulence and significant cloud cover between 2000 ft and 4000 ft in and around the Madrid-Barajas Airport. This prevented the crew from making a safe visual approach, and they probably did not have the runway in sight.

After the second failed landing attempt, the aircraft was diverted to the Madrid Getafe Air Base, probably because ATS thought that a third attempt would entail delays and safety risks for other traffic arriving at the Madrid-Barajas Airport, but not because the weather conditions were clearly better at the Madrid-Getafe Airport. The clouds were just as low, though perhaps not as dense on the surface, which helped with the landing.

Also worth noting is the communication made at 14:46 between approach (APP) and the tower at the Getafe Air Base (TWR GE), in which APP reported that the crew did not speak English well and were unable to clearly describe the emergency they were experiencing.

Their English proficiency was rated as 4, which should have been sufficient to correctly communicate the nature of the problem.

The problems maintaining the basic flight parameters due to the absence of automatic control systems indicates that neither the decision making nor the cooperation between the crew were adequate.

All of these aspects, which could be the subject of a safety recommendation, were already noted by the operator in its report on the event; as a result, no additional recommendations are necessary.

The operator also noted the need to track the defects associated with the autopilot system.

3. CONCLUSIONS

3.1. Findings

- The aircraft took off from runway 14L at the Madrid-Barajas Airport (LEMD).
- Its destination was the Kaunas Airport (EYKA) in Lithuania.
- On board were 2 pilots, 6 flight attendants and 57 passengers.
- The aircraft's documentation was valid.
- The captain had a valid type rating instructor (TRI(A)) rating.
- Both pilots had an English level of 4 annotated in their respective licenses.
- The crew had valid licenses and medical certificates.
- The LH autopilot was inoperative before takeoff.
- The MEL allows operating with the LH autopilot inoperative.
- The RH autopilot was set up to be displayed at both positions.
- During the climb, the RH autopilot became inoperative.
- The crew decided to return to the departure airport when both autopilots became inoperative.
- The RH flight director was set up to be displayed at both positions, but they did not engage it.
- They were unable to clearly inform ATS what kind of malfunction they had.
- They made two unsuccessful landing attempts on runway 18L in IFR conditions.
- ATS diverted the flight to the Getafe Air Base (LEGT), where the weather conditions were better.
- They landed at the Madrid Getafe Air Base on the first attempt.

3.2. Causes/Contributing factors

The investigation has determined that the incident was caused by the problems the crew had operating the aircraft in instrument flight conditions after losing both of the aircraft's automatic flight systems.

4. RECOMMENDATIONS

None.

ANNEX 1. DESCRIPTION OF THE AUTOPILOT

A. (Auto Flight). General description and operation.

According to the AMM, the automatic flight control system (AFCS) in the B737 500 consists of three independent subsystems:

These systems provide control of the airplane and automatic stabilization about the pitch and yaw axes.

The DFCS is a two-axis system (pitch and roll) that operates the elevators and ailerons to automatically maintain altitude and indicated airspeed and to steer the airplane, as well as to perform autolandings. The control functions also translate into flight director commands, which are shown in the electronic attitude direction indicator (EADI) displays of the pilots, thus providing command indications during manual operation or allowing the pilots to monitor the operation of the autopilot.

The autothrust system maintains the Mach number or indicated airspeed during cruise that was previously set, and it also maintains any previously selected engine thrust settings, when performing takeoffs controlled by the flight director, or approaches and landings controlled by the autopilot-flight director, by adjusting the engine thrust levers.

The SP300 digital flight control system (DFCS) installed on the B737 500 includes the following functions:

- Autopilot
- Flight director
- Mach trim
- Speed trim
- Altitude alert

The two DFCS channels are independent, such that the flight director's indications for the captain are provided by "A" flight control computer (FCC A) and the flight director's indications for the first officer are provided by FCC B.

The purpose of the FCC is to receive inputs on the various modes and signals from the sensors, process them and provide outputs for the control surfaces, namely the ailerons, elevator and rudder. The two FCCs are identical and interchangeable.

The diagram below, which shows an outline of the digital flight control system, is taken from the AMM.




Figure 2. Diagram of the digital flight control system in the AMM

B. Mach / Airspeed indicators

The pilots each receive data for the information on indicated airspeed, Mach number and the maximum operating speed on their own air data computer through two Mach/airspeed electronic indicators.

The speed cursor that is located on these indicators is a moving bug that indicates the selected speed. It can be positioned automatically or manually, depending on how the airspeed cursor control is set.

In automatic mode, it can be positioned through its associated flight control computer (FCC) using the inputs to the flight management computer (FMC) or the speed selector on the mode control panel (Autopilot Flight Director System – AFDS).

Each speed cursor can also be positioned manually.

The airspeed cursor control has two positions:

- Pushed in to select automatic mode.
- Pulled out to select manual mode.

The speed cursor flag is shown when, in automatic mode, the signal for the speed cursor as determined by the AFDS FCC is not reliable.

Figure 3 shows an extract from the B-737 500 FCOM that highlights these three elements in the Mach/airspeed indicator, namely the airspeed cursor control (#5), the airspeed cursor (#6) and the airspeed cursor flag (#9).




Figure 3. Airspeed indicator

5 Airspeed Cursor Control

If pushed in, it is in automatic mode and then the airspeed cursor is positioned by the AFDS FCC.

If pulled out, it is in manual mode and the airspeed cursor is adjusted by turning the knob.

6 Airspeed Cursor

Can be positioned manually or automatically depending on the position of the airspeed cursor control.

9 Airspeed Cursor Flag

In manual mode, it is retracted, and in automatic mode, it is visible when the airspeed cursor signals determined by the AFDS FCC are not reliable.



Figure 4. Photograph of the airspeed indicator

C. Autopilot Flight and Director System.

The autopilot flight director system (AFDS) is a dual system consisting of two flight control computers (FCC) and one mode control panel (MCP).

To operate the autopilot (A/P), the FCCs, identified as A and B, send control signals to their respective pitch and roll hydraulic servos, which operate the flight controls by way of two separate hydraulic systems. To operate the flight director (F/D), each FCC positions the F/D bars in its respective ADI.

Autopilot Engagement Criteria

Each A/P can be engaged by pushing a separate CMD or command wheel steering (CWS) engage switch. A/P engagement in CMD or CWS is inhibited unless no force is

being applied to the control wheel and the STAB TRIM AUTOPILOT cutout switch is in NORMAL.

If the autopilot is engaged in CMD, with one or two flight directors (F/D) operating in control mode and the F/D command bars are not centered to within approximately half of the scale, the A/P is engaged automatically in CWS for pitch and roll and the F/D command bars disappear.

Flight Director Display

Turning a F/D switch ON displays command bars on the respective pilot's attitude indicator if command pitch and roll modes are engaged. F/D commands operate in the same command modes as the A/P except:

- the takeoff mode is a F/D only mode.
- dual F/D guidance is available for single engine operation.
- the F/D has no landing flare capability. F/D command bars retract from view at approximately 50 feet RA on an ILS approach.

Normally, FCC A drives the captain's command bars and FCC B drives the first officer's command bars. With both F/D switches ON, the logic for both pilots' F/D modes is controlled by the master FCC, and both FMA displays show the same mode status.

The master FCC is indicated by illumination of the respective master (MA) F/D indicator light. The master FCC is determined as follows:

- With neither A/P engaged in CMD, the FCC for the first F/D turned on is the master.
- With the A/P engaged in CMD, its associated FCC is the master FCC, regardless of which F/D is turned ON first.
- With both A/Ps engaged in CMD, the FCC for the first A/P in CMD is the master FCC, regardless of which F/D is selected first

F/D modes are controlled directly from the respective FCC under certain conditions. This independent F/D operation occurs when neither A/P is engaged in CMD, both F/D switches are ON and one of the following mode conditions exists:

- APP mode engaged with LOC and G/S captured.
- GA mode engaged and below 400 feet RA.
- TO mode engaged and below 400 feet RA.

Independent F/D operation is indicated by illumination of both MA lights. When independent operation terminates, the MA light extinguishes on the slaved side.

AFDS Status Annunciation

The following AFDS status annunciations are displayed in the A/P status display, located on the EADI:

- CMD (one or both autopilots are engaged).
- FD (the F/D is ON and the autopilot is either OFF or engaged in CWS).
- CWS P (pitch mode engaged in CWS).
- CWS R (roll mode engaged in CWS).

Figure 5, taken from the FCOM, shows the flight mode annunciations (FMA).




Figure 5. Flight mode annunciations (FMA)

Flight Director

Figure 6 is an extract taken from the FCOM that shows the controls and indications on the mode control panel (MCP) associated with the master F/D indicating light, the F/D switch and the A/P control switch located on the MCP.




Figura 6. Controles e indicaciones en la MCP

1 Autopilot Engage Paddle

CMD mode:

- Engages the associated A/P.
- Enables all command modes.
- Shows CMD on the A/P status display.
- Selecting the second A/P in CMD disengages the first A/P selected, unless it is in APP mode.
- Allows CWS operation

CWS engages if:

- Pitch or roll mode not selected.
- Pitch or roll mode deselected.
- Pitch or roll mode manually overridden with control column force.

During F/D only operation while pitch or roll commands are more than ½ scale from center, pushing a CMD A or B switch engages the A/P in CWS for pitch and/or roll and the related F/D bar(s) retract.

CWS mode:

- Engages A/P.
- Engages pitch and roll modes in CWS.
- Displays CWS P and CWS R in A/P status display.
- CMD is not displayed in A/P status display.
- F/Ds, if ON, display guidance commands and FD annunciates in A/P status display. A/P does not follow commands while in CWS.
- A/P pitch and roll controlled by pilot with control wheel pressure.




Figure 6. Autopilot Engage Paddle

When control pressure released, A/P holds existing attitude. If aileron pressure released with 6 degrees or less bank, the A/P rolls wings level and holds existing heading. Heading hold feature inhibited:

- below 1500 feet RA with gear down
- after LOC capture in APP mode
- after VOR capture with TAS 250 knots or less.

2 Master (MA) Flight Director Indicators (white letters)

If a F/D switch is ON, the light indicates which FCC is controlling the F/D modes.

- illuminated – related FCC is controlling F/D modes.
- extinguished – F/D modes are controlled from opposite FCC.
- both lights illuminated – each FCC is controlling modes for related F/D.

3 Flight Director (F/D) Switch

Left F/D switch activates the command bar on the Captain's attitude indicator. Right F/D switch activates the command bar on the First Officer's attitude indicator.

In the ON position:

- Enables command bar display on related ADI.
- Command bars are displayed if command pitch and/or roll modes are engaged.
- FD shown on the A/P status display if the A/P is OFF or engaged in CWS.
- On ground, arms pitch and roll modes for engagement in TP/GA and HDG SEL when TOGA switch is pushed.

- On ground, arms pitch and roll modes for engagement in TO/GA and wings level when TOGA switch is pushed.
- In flight with A/P ON and F/Ds OFF, turning a F/D switch ON engages F/D in currently selected A/P modes.

In the OFF position, the command bars retract from the related ADI.

D. SPEED TRIM FAIL and MACH TRIM FAIL indications

10 SPEED TRIM Failure (FAIL) Light

Speed Trim System

The speed trim system is designed to improve flight characteristics during operations with a low weight, aft center of gravity and high thrust. It monitors inputs of stabilizer position, thrust lever position, airspeed and vertical speed to trim the stabilizer. It operates most frequently during takeoffs and go-arounds.

When illuminated, the amber SPEED TRIM FAIL light, located in the forward overhead panel, indicates:

- Failure of the speed trim system.
- Failure of a single FCC channel when MASTER CAUTION light recall is activated and light extinguishes when Master Caution System is reset.

11 MACH TRIM Failure (FAIL) Light

The Mach trim system provides speed stability at higher Mach numbers. Mach trim is automatically accomplished above Mach 0.615 by adjusting the elevators with respect to the stabilizer as speed increases.

When illuminated, the amber MACH TRIM FAIL light, located in the forward overhead panel, indicates:

- Failure of the Mach trim system.
- Failure of a single FCC channel when MASTER CAUTION light recall is activated and light extinguishes when Master Caution System is reset.

Figure 7, taken from the FCOM, shows the locations of these lights on said panel.





Figure 7. MACH/SPEED TRIM FAIL lights

ANNEX 2
COMPLETE FLIGHT PATH



ANNEX 3
FLIGHT PARAMETERS

